

Entrance-Before renovation



During



After renovation





Before land slide

After land slide





During renovation work



After renovation



Floor-before renovation



During




After renovation

Dancing Bhairavi (Bala Bhairavi), Kamakhya, Dist.-Kamrup, Assam



Image damaged during land slide



After joining the image by Masons from Odisha




After renovation placed over a pedestal





Approach pathway- Before





Before renovation



After renovation